








## STANDARD GAUGE SCALE RANGES

Standard marking and increments for accuracy class 1 and 1,6

Round scales expand over 270 °c  
Dual & customised scales are available on request.

Scale Range	Scale Markings	Increments
0...1	 0 0.2 0.4 0.6 0.8 1	0.02
0...10	0 2 4 6 8 10	0.2
0...100	0 20 40 60 80 100	2
0...1000	0 200 400 600 800 1000	20
-1...0	-1 -0.8 -0.6 -0.4 -0.2 0	0.02
-10...0	-10 -8 -6 -4 -2 0	0.2
-100...0	-100 -80 -60 -40 -20 0	2
0...2.5	0 0.5 1.0 1.5 2.0 2.5	0.05
0...25	0 5 10 15 20 25	0.5
0...250	0 50 100 150 200 250	5
0...2500	0 500 1000 1500 2000 2500	50
0...500	0 100 200 300 400 500	10
-100...0...900	-100 0 100 200 300 400 500 600 700 800 900	20
-100...0...150	-100 50 0 50 100 150	5
-100...0...2400	 -100 0 400 900 1400 1900 2400	50
0...0.8	 0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 0.8	0.01
0...8	0 1 2 3 4 5 6 7 8	0.1
0...80	0 10 20 30 40 50 60 70 80	1
0...800	0 100 200 300 400 500 600 700 800	10
0...8000	0 1000 2000 3000 4000 5000 6000 7000 8000	100
0...1.6	0 0.2 0.4 0.6 0.8 1.0 1.2 1.4 1.6	0.02
0...16	0 2 4 6 8 10 12 14 16	0.2
0...160	0 20 40 60 80 100 120 140 160	2
0...1600	0 200 400 600 800 1000 1200 1400 1600	20
-100...0...700	-100 0 100 200 300 400 500 600 700	2
-100...0...1500	-100 0 100 200 300 400 500 600 700 800 900 1000 1100 1200 1300 1400 1500	20
0...4	 0 1 2 3 4	0.1
0...40	0 10 20 30 40	1
0...400	0 100 200 300 400	10
0...4000	0 1000 2000 3000 4000	100
0...200	0 50 100 150 200	5
-100...1300	-100 0 100 200 300	10
0...0.6	 0 0.1 0.2 0.3 0.4 0.5 0.6	0.01
0...6	0 1 2 3 4 5 6	0.1
0...60	0 10 20 30 40 50 60	1
0...600	0 100 200 300 400 500 600	10
0...6000	0 1000 2000 3000 4000 5000 6000	100
0...300	0 50 100 250 200 250 300	5
-100...500	-100 0 100 200 300 400 500	10